

FITNESS CERTIFICATE

- 1 Name of the officer : **Rajeev R ,Assistant Engineer**
- 2 Name of School : **Al - Ameen Public School ,
Pathanapuram**
- 3 Location with name of Education
Dist./ Sub Dist. : **Punalur/Punalur**
- 4 Classification of building as specified
in column 4 of the application for
fitnes certificate & size : **Permenant**
Block No 1
34.32x7.40x3.60m GF RCC roof
34.32x7.40x3.60m FF RCC roof
- 5 Period for which the certificate is issued : **2023-24**
- 6 Nature of defect if any :
- a) Foundation and Basement : **Nil**
- b) Superstructure : **Nil**
- c) Doors And Windows : **Nil**
- d) Wood work wrought and put up : **Nil**
- e) Roof : **Nil**
- f) Flooring : **Nil**
- g) Miscellaneous(Cracks etc) : **Nil**
- 7 Any major defect noticed which will
render the building unsafe in any manner : **No**
- 8 Whether maintenance work have been
done properly : **Yes**
- 9 Whether the structure is sound or not for
conducting classes : **The structure is sound under normal
weather Condition**


Note

- 1 The stability of the structure should be examined also with reference to location altitude intensity of wind ,exposure to flood etc
- 2 An additional observations if demand necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me
on...29..05.2023..... and found to be **fit** to conduct classes for the period
of ... 2023-24....for the reasons stated above

Place : Pathanapuram
Date : 29.05.2023



Signature 
Designation **ASSISTANT ENGINEER**
LSGD Section
Pathanapuram Grama Panchayat