

## FITNESS CERTIFICATE

- 1 Name of the officer : Praveen P Krishnan, Assistant Engineer
- 2 Name of School : Al - Ameen Public School ,  
Pathanapuram
- 3 Location with name of Education  
Dist./ Sub Dist. : Punalur/Punalur
- 4 Classification of building as specified  
in column 4 of the application for  
fitnes certificate & size : Permenant  
Block No 1  
34.32x7.40x3.60m GF RCC roof  
34.32x7.40x3.60m FF RCC roof
- 5 Period for which the certificate is issued : 2025-26
- 6 Nature of defect if any :  
a) Foundation and Basement : Nil  
b) Superstructure : Nil  
c) Doors And Windows : Nil  
d) Wood work wrought and put up : Nil  
e) Roof : Nil  
f) Flooring : Nil  
g) Miscellaneous(Cracks etc) : Nil
- 7 Any major defect noticed which will  
render the building unsafe in any manner : No
- 8 Whether maintenance work have been  
done properly : Yes
- 9 Whether the structure is sound or not for  
conducting classes : The structure is sound under normal  
weather Condition

### Note

- 1 The stebility of the structure should be examined also with refference to location altitude intensity of wind ,exposure to flood etc
- 2 An additional observations if demand necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me  
on...16..07.2025..... and found to be fit to conduct classes for the period  
of ... 2025-26....for the reasons stated above

Place : Pathanapuram  
Date : 16.07.2025

Signature  
Designation

ASSISTANT ENGINEER  
LSGD Section  
Pathanapuram Grama Panchayat